

PORT OF EDMONDS

BOATYARD BEST MANAGEMENT PRACTICES (BMP's)

- BMP-1** Conduct all boatyard activities in accordance with the listed environmental Best Management Practices, to prevent water, soil and air pollution.
- BMP-2** Before commencing any work, boatyard occupants are required to read and understand the BMP's and sign off on them.
- BMP-3** When stripping, sanding, scraping, painting, coating and/or varnishing any portion of the vessel, all particles, oils, grits, dusts, flakes, chips, drips, sediments, debris and other solids shall be collected and managed to prevent release into the environment. Drop cloths, tarps, drapes, shrouding or other protective devices are required to collect and manage such material and must be adequately secured around the vessel to resist wind from causing a release of collected solids. Port Employees will provide tape and plastic for use as drop cloths and enclosures. Any lose material on ground must be cleaned immediately following work.
- BMP-4** Work yard spaces must be cleaned daily, the Port will charge a clean up fee if spaces are not cleaned at the end of the day, min charge \$40.00 per person per 1/2 hour per day.
- BMP-5** Drip pans or other containment devices shall be used during all petroleum product transfer operations. A spill response kit is available in the work yard. Use oil absorbent pads to contain and clean up spills. Promptly notify the Port of any spills that enter, or threaten to enter, the storm drain.
- BMP-6** No storage of paints, solvents and other chemicals is allowed on the ground under or around the boat
- BMP-7** No containers larger than 5 gallons allowed in the work yard.
- BMP-8** Bilges must be cleaned prior to doing work that penetrates the hull. Absolutely no bottom washing allowed in the work yard.
- BMP-9** Contractors/vendors are responsible for disposing of all waste, no dumping of waste in the storm drains. Customers must dispose of collected waste solids in the waste solids drum provided by the Port and can dispose of used plastic or drop cloths to the dumpster once the collected solids have been removed.
- BMP-10** All spray painting must be pre-approved by Marina Operations Supervisor prior to starting work.
- BMP-11** Only vacuum sanders allowed in work yard, non-vacuum grinders are prohibited.
- BMP-12** Abrasive grit blasting and ice blasting are prohibited.
- BMP-13** Work yard occupants shall coordinate disposal of hazardous waste with Port Employee's.
- BMP-14** The use of antifouling paint containing Tributyl Tin is prohibited.
- BMP-15** Brooms, dust pans, and shop vacuums are available for check-out. If vacuums, dust pans and brooms are checked out it is the owners responsibility to return them when work is completed or the owner of the boat will be charged a replacement fee. Do not clean area by hosing down with water.
- BMP-16** Zincs used as sacrificial anodes shall not be disposed of into the water or into the trash. Spent zincs are to be placed in the Port's covered container for recycling.

Please Note: Work Yard users will be charged a \$100.00 violation fee for any violation of the above BMP's.

Customer Initials _____ Date _____